



Symbol	Unit: mm		
	Min	Typ.	Max
A	0.900	0.950	1.000
A3	0.254REF.		
D	4.900	5.000	5.100
E	5.900	6.000	6.100
D1	3.750	3.950	4.150
E1	3.300	3.450	3.600
D2	4.800	4.900	5.000
E2	5.650	5.750	5.850
k	1.200	1.350	1.500
b	0.350	0.400	0.450
e	1.220	1.270	1.320
L	0.510	0.610	0.710
H	0.510	0.610	0.710

单位: mm